TECH TIPS

Dixie Part Numbers: A-1548 A-1705 A-1706 A-6548
S-1468 S-1490 S-1511 S-80060
S-80302

Applications:
2007 – 2008 Cadillac Escalade
2007 – 2008 Chevrolet Avalanche
2007 – 2008 Chevrolet Silverado
2007 – 2008 Chevrolet Suburban
2007 – 2008 Chevrolet Tahoe
2007 – 2008 GMC Sierra
2007 – 2008 GMC Yukon

Condition: The technician may observe that the battery post terminal is cracked.

Cause: When removing and reinstalling the battery post cable terminals do not over-torque them. They are designed with a special T-shaped bolt that tightens the terminal around the post. Over tightening the bolt will cause the terminal to crack.

Correction: The terminal post bolt requires 44 lb in or 5 Nm of torque. If the terminal has cracked it is sold separately from the lead as part number 19116852.

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.