TECH TIPS

Dixie Part Numbers: A-9378 A-80208 S-1430 S-1512 S-1515 S-1517

Applications: 2005 – 2007 Cadillac XLR (up to VIN 75600571)
2005 – 2007 Chevrolet Corvette (up to VIN 75112132)

Condition: Some vehicle operators may complain that the battery is dead and/or the vehicle does not crank and/or start.

Cause: A possible cause for the above is that the software for the remote control door lock receiver from the factory had an anomaly that would cause the system to draw an additional 30 mA when in the passive mode.

Correction: The vehicle manufacturer **has** released a calibration file for the remote control door lock receiver to correct the problem. Ensure that the latest calibration file has been loaded into the system, as earlier attempts to correct this problem did not work properly.

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.