



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Buick Enclave¹
2010 Chevrolet Equinox¹
2010 Chevrolet Traverse¹
2010 GMC Acadia¹
2010 GMC Terrain¹

¹With automatic transmission code W (Warren) on the identification label (the 7th digit on the label) and manufactured between May 19, 2010 and June 1, 2010.

Condition: The operator of the vehicle may complain that the engine does not start, crank and the starter solenoid does not click.

Cause: A potential cause for the above condition is a bent terminal in the control solenoid valve and transmission control module assembly.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures.

