



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Cadillac SRX - Non-US models equipped with RPO ULS, steering column lock control.

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- Intermittently the engine does not start
- A steering column lock light is on
- A service steering column lock message is displayed in the diagnostic information center.

The technician may find code B2515 or B305A stored in the Body Control Module.

Cause: A potential cause for the above condition is a flaw in the Steering Column Lock Module.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures if applicable.