



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Buick LaCrosse¹
2010 Cadillac SRX¹
2010 Chevrolet Equinox¹
2010 GMC Terrain¹

1) Equipped with a 3.0L or 3.6L V6 engine and built prior to February 27, 2010

Condition: The operator of the vehicle may complain of intermittent belt noise.

Cause: A potential cause for the above condition is one of the following:

- The power steering pump may be misaligned.
- The accessory drive pulley may be misaligned or bent.
- The drive belt may be worn and require replacing.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures if applicable.

