



# TECH TIPS

**Dixie Part Numbers:** S-1512

**Applications:** 2005 Chevrolet Corvette –With Manual Transmission

**Condition:** The operator of the vehicle may complain of an intermittent no crank and no start condition. The technician may observe that recharging the battery and/or disconnecting and reconnecting the battery cables temporarily corrects the problem.

**Cause:** A potential cause for the above conditions is a flaw in the steering column lock motor assembly.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures which recommend replacing the steering column lock motor assembly.

