



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2007 Saturn Aura Greenline Hybrid™  
2007 Saturn Vue Greenline Hybrid™

**Condition:**  
The battery and/or check engine light may come on. Using a scan tool may reveal codes P1A59 alone or with a second code of P1A5A.

**Cause:**  
A possible cause could be module voltage imbalance or corrosion.

**Correction:**  
If the hybrid module voltage imbalance exceeds 0.6V or if corrosion is present the 3 batteries must be replaced following the manufactures recommended procedures.

