



TECH TIPS

Dixie Part Numbers: A-1759 A-80221 S-6276 S-6281
S-6282

Applications: 2007 – 2008 Audi Q7

Condition: The operator of the vehicle may complain of a dead battery, that the EPC light is on or that the engine fails to start. The technician may observe that code P0088 *Fuel Pressure too high/sporadic* is recorded in the system.

Cause: A possible cause for the above conditions is a loose battery positive cable at the battery and/or on the plenum box connection.

Correction: Follow the manufacturers recommended diagnostic and repair procedures, which include inspecting the connection points for damage (such as arcing), replacing the terminals, if damaged, and tightening the connectors to the proper specifications.

