



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2004 – 2008 Bluebird Vision Conventional Style Buses
(Excluding School Buses)

Condition: The operator of the vehicle may complain of intermittent cranking, a failure to crank or an engine compartment fire.

Cause: A potential cause for the above conditions is that the starter battery cable may chafe against the power steering hose, and overtime result in a faulty continuity to ground.

Correction: Follow the manufacturers recommended diagnostic and repair procedures which include inspecting for clearance and replacing the battery cables when required.

