



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2008 – 2011 Mack GU Series Truck

**Conditions:** The operator of the vehicle may observe various electrical functions operating erratically up to and including an engine compartment fire.

**Cause:** A potential cause for the above conditions is a fault in routing of the battery pack wiring harness and clips used. The battery cables may contact frame hardware, and over time the chafing may destroy the insulation resulting in a faulty continuity to ground.

**Correction:** Follow the manufacturer's recommended repair procedure, which includes replacing the leads if damaged and rerouting them to prevent chafing.

