



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2010 Buick Lucerne 3.9L

**Conditions:** The operator of the vehicle may complain that the vehicle will crank but not start when the key is turned to the crank (start) position.

**Cause:** A potential cause for the above condition is a poor connection to the rear fuse block located under the rear seat. The poor connection prevents power from being supplied to the fuel pump.

**Correction:** Inspect and repair the above condition following the manufacturer's recommended diagnostic and repair procedures.

