



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2012 Mack LEU (compressed natural gas models)
2011 – 2012 Mack MRU (compressed natural gas models)

Conditions: The operator of the vehicle may complain of erratic electrical problems up to and including an electrical fire in the engine compartment

Cause: A potential cause for the above condition is a design flaw where the alternator cable was routed in close proximity to the high pressure power steering hose, allowing the cable to chafe on the steel braiding and become short circuited to ground.

Correction: Follow the manufacturer's repair procedures which include installing a bracket to prevent the battery cable from chafing on the high pressure power steering hose.

