



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2012 Chevrolet Sonic

Conditions: The operator of the vehicle may complain that the service engine soon light is illuminated. The technician may find diagnostic trouble code C0550 43 stored in the system memory.

Cause: A potential cause for the above conditions is the electronic steering control module, which at lower voltages, will activate the trouble code.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable.

