



TECH TIPS

Dixie Part Numbers: S-1422, S-1426

Applications: 2000 Chevrolet Cavalier
2000 Chevrolet Malibu
2000 Oldsmobile Alero
2000 Pontiac Grand Am
2000 Pontiac Sunfire

Condition: The operator of the vehicle may complain of hard starting, no starting or hesitation when driving. The vehicle may have had starters burnt out.

Cause: A possible cause is a restricted or blocked fuel sender strainer.

Correction: The fuel sender strainer should be replaced with a new one, part number 88891094 following the manufacturer's recommended procedures.

