



# TECH TIPS

**Dixie Part Numbers:** S-1519

**Applications:** 2007 Jeep Wrangler 3.8L

**Condition:** The operator of vehicle may complain of one or more of the following vehicle conditions:

- Extended cranking cycle
- Multiple crank cycles prior to the engine starting

**Cause:** A potential cause for the above conditions is an incorrectly positioned camshaft sensor resulting in the camshaft sensor being too close and/or coming in contact with the camshaft gear

**Correction:** Follow the manufacturer's recommended procedures to check and/or replace the cam shaft sensor.

