



TECH TIPS

Dixie Part Numbers: A-1759 NA

Applications: 2007 – 2009 Audi Q7 3.6L

Condition: The operator of the vehicle may complain of the following conditions:

- The alternator warning light is on.
- There is noise coming from the engine area.
- The steering is sluggish.

The technician may observe that the belt tensioner spring is broken.

Cause: The factory supplied tensioner... left something to be desired in regards to durability. The manufacturer recognized this and revised the design of the belt, tensioner and associated pulleys.

Correction: Follow the manufacturer's recommended procedures to change the belt, the belt tensioner, idler pulley and coolant pump pulley.

