



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:**

- 2009 Buick Allure
- 2009 Buick Lacrosse
- 2009 Buick Lucerne
- 2009 Cadillac DTS
- 2009 Chevrolet Impala
- 2009 Chevrolet Malibu
- 2009 Chevrolet TrailBlazer
- 2009 GMC Envoy
- 2009 Pontiac G6
- 2009 Hummer H2
- 2009 Hummer H3
- 2009 Saab 9-7X
- 2009 Saturn AURA

NOTE: Applicable to vehicles equipped with OnStar® (generation 8.0L)

**Condition:** The operator of the vehicle may complain that the vehicle is hard to start or has a low/dead battery after parking the vehicle. They may also notice that the LED for the OnStar® is not flashing and none of the buttons respond when pressed on the OnStar® device.

**Cause:** A potential cause for the above conditions is excessive parasitic drain due to the calibration file in the OnStar® module.

**Correction:** Follow the manufacturer's recommended procedures for diagnosing and correcting the OnStar® module calibration file.