



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2010 Buick LaCrosse  
2010 Cadillac SRX

**Condition:** The operator of the vehicle may complain of hard starting, no starting or frequent dead battery occurrences.

**Cause:** A potential cause for the above condition is a software flaw in the keyless entry system which prevents other modules from going into the sleep mode, thereby creating excessive parasitic or quiescent draw.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures to update the required calibration files.

