



TECH TIPS

Dixie Part Numbers: A-1366 S-1409

Applications: 1991 – 1993 Saturn SC Series
 1991 – 1993 Saturn SW Series

Condition: The above vehicle may have a catastrophic electrical failure up to and including an engine fire.

Cause: The above application was subject to a recall as there was no protection installed in the wiring between the alternator and battery.

Correction: Follow the manufacturer's recommended repair procedures to replace the wiring harness with one containing the circuit protection.

