



TECH TIPS

Dixie Part Numbers: S-2095, S-2098, S-8423, 243-25101

Applications: 2000 – 2001 Ford F Series with the Bi-Fuel option

Condition: Some vehicle operators may complain of a no start condition when operating in the alternate fuel mode.

Cause: A possible cause is a solenoid failure in the fuel tank due to corrosion.

Correction: Follow the manufacturer's recommended diagnostic procedures to verify if the solenoid tank valve coil is functioning correctly.

