



TECH TIPS

Dixie Part Numbers:	S-2059	S-2065	S-2069	S-2070
	S-2071	S-2074	S-2075	S-2076
	S-2079	S-2083	S-2087	S-2095
	S-8423	S-82059		

Applications: 1996 – 2000 Ford Contour Bi-Fuel (propane or natural gas) without coolant lock-off.
1996 – 2002 Ford F-150 Bi-Fuel (propane or natural gas) without coolant lock-off.
1997 Ford F-250 Bi-Fuel (propane or natural gas) without coolant lock-off.
1998 – 1999 Ford E Series Bi-Fuel (propane or natural gas) without coolant lock-off.
2000 – 2001 Ford Super Duty F Series Bi-Fuel (propane or natural gas) without coolant lock-off.

Condition: The operator off the vehicle may complain that the vehicle does not start in the alternate fuel mode

Cause: A possible cause for the above failure is a stuck low flow injector on the Compuvalve, possibly as a result of contaminated fuel.

Correction: **Warning:** When working on fuel related systems ensure that there are no sources of ignition. Also propane and natural gas systems must have the pressure relieved before working on the system or damage or injury may result.



Follow the manufacturer's recommended procedures for inspection and repair of the Compuvalve system. Working on this part of the fuel system requires particular attention to cleanliness and avoiding contamination!

Resision 20090709: Updated listing to include Contour, E Series and more then F-150 Series

REV: 20090709

Courtesy of APRA

TSB_224.doc

Dixie Tech Tips are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the Tech Tip applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed without written permission.