



TECH TIPS

Dixie Part Numbers: A-248 A-275 A-2031 A-2033
 A-761 A-8490 S-2059 S-2079
 S-8423 S-82059

Applications: 1997 Ford Econoline – E Series Van

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- Various erratic electrical problems.
- Major electrical failure.
- Under hood fire.

Cause: A potential cause for the above condition is that the battery cable and starter wiring harness was routed in close proximity to the right engine mount and over time may chaff and short circuit to ground.

Correction: The manufacturer recommends inspecting the wiring, repairing any damage, adding insulation and re-routing the wiring harness away from the engine mount (when applicable).

Nanny's Simple BBQ Sauce

½ Cup ketchup
2 Tbsp Molasses
2 Tbsp Butter
2 Tbsp Water
1 Tbsp Worcestershire sauce

Cook to heat and blend

Use as a base and add spices or a few drops of liquid smoke

Ribs

For cooking Ribs – 450 for 30 minutes in a covered roasting pan with the ribs on a rack.

Reduce the temperature to 375 and cook for ½ hour. Drain off the fat and brush both sides with the sauce. Cook for an additional ½ hour uncovered.

