



TECH TIPS

Dixie Part Numbers: S-1514 S-6284 S-80189
S-80190 S-80191 S-80347

Applications: 2006 – 2007 Kia Sedona
2007 Hyundai Entourage production range February 15, 2006 – April 18, 2007.

Condition: The operator of the vehicle may complain of intermittent no crank conditions.

Cause: A potential cause for the above condition is a faulty factory installed anti-theft alarm relay located in the IPM module. If you are curious like me you may discover that “IPM” according to North Dakota State University is *Integrated Pest Management*...a little different view of the would be vehicle thief.

Correction: Follow the manufacturers recommend procedures for testing the IPM module relay and replace the IPM only if required.

