



# TECH TIPS

**Dixie Part Numbers:** S-6071 S-6098 S-6100

**Applications:** 1980 – 1984 Volkswagen Rabbit Diesel

**Condition:** The operator of the vehicle may comment on hard start or no start conditions. This will occur more often when the engine is hot (hot soak).

**Cause:** A potential cause for the above is inadequate voltage at the starter due to high voltage drops.

**Correction:** The manufacturer has released a relay kit, part number 191-911-251, to improve the current available to the starter. A voltage drop test will assist in determining if the kit is required.

