



TECH TIPS

Dixie Part Numbers:	A-6407	A-6571	A-6573	A-9361
	A-9497	A-9499	A-9523	A-9524
	A-9531	A-9532	S-6229	S-6258
	S-6565	TBA		

Applications: 2006 – 2010 BMW X5
2008 – 2010 BMW X6

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- The engine is hard to start or will not start.
- The engine goes into “limp home mode”
- The battery is discharged
- Various error messages displayed

The technician may find a variety of diagnostic trouble codes retained in the system.

Cause: A potential cause for the above conditions is a flaw in the DME/DDE module and wiring plug in connections which allowed water to contaminate the electronics inside the box.

Correction: Follow the manufacturer’s recommended procedures to diagnose and repair the electronics and box when required.