



TECH TIPS

Dixie Part Numbers:	A-1745	A-1747	A-1759	A-6376
	A-6417	A-6418	A-6419	A-6534
	A-6574	A-9501	A-9502	A-9503
	A-9527	A-9528	A-9529	A-9530
	A-9536	A-80205	A-80212	A-80213
	A-80214	A-80219	A-80220	A-80221
	S-6172	S-6209	S-6210	S-6211
	S-6254	S-6262	S-6263	S-6264
	S-6265	S-6267	S-6268	S-6276
	S-6281	S-6282	S-6289	S-6290
	S-6557	S-6558	S-6561	TBA

Applications: 2005 – 2012 Audi All Models with Aftermarket Window Tinting

Condition: The operator of the vehicle may complain of a variety of electrical issues. Upon questioning the technician may learn that the vehicle had the windows tinted just prior to the malfunctions occurring.

Cause: A potential cause for the above condition is that the vehicle was designed to prevent water from entering it. Critical electrical components, mounted in the trunk, are not protected from water dripping from the rear window hat shelf, which may occur when window tinting film is applied.

Correction: Follow the manufacturer's recommended procedures if installing window tinting by either covering the hat shelf or removing the electrical components.

