



TECH TIPS

Dixie Part Numbers: S-6284 S-80189 S-80190 S-80191
S-80347 S-80365 S-80395 TBA

Applications: 2008 – 2009 Jeep Commander (International Models)
2008 – 2009 Jeep Grand Cherokee (International Models)
2008 – 2010 Chrysler 300 (International Models)
2009 – 2010 Chrysler Town and Country (International Models)
2009 – 2010 Dodge Caravan (International Models)
2009 – 2010 Dodge Journey

Conditions: The operator of the vehicle may complain that intermittently the engine fails to crank or start.

Cause: A potential cause for the above condition may be the program file located in the Wireless Ignition Node Module.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures which include verifying that the module was manufactured by Continental Siemens Automotive Systems (variant code 4) and updating the program file when required.