



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2009 Buick Enclave  
2009 Chevrolet Cobalt  
2009 Chevrolet HHR  
2009 Chevrolet Malibu  
2009 Chevrolet Traverse  
2009 GMC Acadia  
2009 Pontiac G5  
2009 Pontiac G6  
2009 Saturn Aura  
2009 Saturn Outlook  
2011 Chevrolet Colorado  
2011 GMC Canyon

**Condition:** The operator of the vehicle may complain of intermittent no crank condition, the vehicle rolls/moves while cranking, or that the vehicle rolls when in “park”.

**Cause:** A potential cause for the above conditions is an improperly installed adjustment clip on the automatic transmission shifter cable.

**Correction:** Follow the manufacturers recommended diagnostic and repair procedures when applicable.