

TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Cadillac CTS

Condition: The operator of the vehicle may complain that the engine fails to start and

that the battery is low or dead.

Cause: A potential cause for the above condition is a software flaw in the

ultrasonic park assist module.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures

which may require reprogramming the park assist module.

ELECTRIC









REV: 20110503 Courtesy of APRA TSB_1006.docx