



TECH TIPS

Dixie Part Numbers: S-1512

Applications: 2005 Chevrolet Corvette –With Manual Transmission

Condition: The operator of the vehicle may complain of an intermittent no crank and no start condition. The technician may observe that recharging the battery and/or disconnecting and reconnecting the battery cables temporarily corrects the problem.

Cause: A potential cause for the above conditions is a flaw in the steering column lock motor assembly.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures which recommend replacing the steering column lock motor assembly.

