



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2010 Buick Enclave 3.6L  
2010 Chevrolet Traverse 3.6L  
2010 GMC Acadia 3.6L  
2010 Saturn Outlook 3.6L

**Conditions:** The operator may complain of extended starter cranking time when the ambient temperature is 10-15°C /50-60°F.

**Cause:** A potential cause for the above condition is a flaw in the initial engine control module calibration file.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures and update the engine control module calibration file only when required.

