



# TECH TIPS

---

**Dixie Part Numbers:** TBA

**Applications:** 2010 – 2011 MCI D4505

**Conditions:** The operator of the vehicle may complain of erratic electrical problems including low/dead batteries, hard starting conditions or an engine compartment fire.

**Cause:** A potential cause for the above condition is water contamination on the alternator battery terminal, causing the terminal to corrode and develop a high voltage drop.

**Correction:** Follow the manufacturer's inspection and repair procedures when applicable.

