



TECH TIPS

Dixie Part Numbers: A-1549 A-1636 A-1645

Applications: 2010 Navistar Workhorse W42
2010 Navistar Workhorse W62
2011 Navistar Workhorse W22
2010 Fleetwood Bounder Class A Motor home
2010 Fleetwood Bounder Classic Class A Motor home
2010 Fleetwood Fiesta Class A Motor home
2010 Fleetwood Southwind Class A Motor home
Various other applications

Condition: The operator of the vehicle may complain of one or more to the following conditions:

- the alternator warning light is on (when applicable).
- the volt meter shows the alternator as not charging or overcharging (when applicable).

Cause: Remy Power Products LLP, the manufacturer of the OE supplied alternator has identified a flaw in the manufacture of the factory-supplied alternators for the above applications.

Correction: Follow the manufacturer's recommended procedures to replace the alternator if not already done. **This procedure does not apply to the units remanufactured by Dixie and applies only to the initial factory installed alternators.** Find out from the owner of the vehicle if the dealer performed the required service, as the alternator may be eligible for replacement under warranty.