



# TECH TIPS

Dixie Part Numbers: S-1449 S-1468 S-1506 S-1511

**Applications:** 2004 – 2007 Chevrolet Colorado  
2004 – 2007 GMC Canyon  
2006 – 2007 Chevrolet TrailBlazer  
2006 – 2007 GMC Envoy  
2006 – 2007 Hummer H3  
2006 – 2007 Saab 9-7X

**Condition:** The operator of the vehicle may complain of an intermittent click no crank or brief crank for a split second then no cranking condition. When cycling the key back to the off position and then initiating the start sequence a second time the vehicle starts with no issue.

**Cause:** The manufacturer of the vehicle is aware of this condition and at this time the cause is not known.

**Correction:** The manufacturer is investigating this issue and at this time there is no known correction.