



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 Chevrolet Aveo
2009 Pontiac G3 (US)
2009 Pontiac Wave (Canada)

Condition: The operator of the vehicle may complain of an intermittent crank without starting condition with the malfunction indicator lamp illuminated. The technician may observe diagnostic trouble codes P0606 and/or P16F3 retained in the system memory.

Cause: A potential cause for the above condition is voltage fluctuations caused from the ignition key cycling.

Correction: The manufacturer has released an updated calibration file for the electronic control module. Follow the manufacturer's recommended procedures for diagnosing the system and updating the calibration files.

