



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2008 BMW 730d
2008 BMW 730Ld
2008 BMW 740d
2008 BMW 740i
2008 BMW 740Li
2008 BMW 750i
2008 BMW 750Li
2008 BMW 760i
2008 BMW 760Li

Condition: The operator of the vehicle may complain that the vehicle fails to crank or start.

Cause: A possible cause is a faulty remote control receiver in the antenna module.

Correction: Follow the manufacturer's recommended procedures when troubleshooting and/or replacing the antenna module.