



# TECH TIPS

**Dixie Part Numbers:** S-6166

**Applications:** 1981 – 1982 Alfa Romeo GTV-6

**Condition:** The operator of the vehicle may complain that the starter does not crank on an intermittent basis.

**Cause:** A potential cause for the above condition is a faulty ignition switch assembly.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures and replace the ignition switch if required.

