



# TECH TIPS

**Dixie Part Numbers:** TBA

**Applications:** 2009 – 2011 Volkswagen Golf 2.0L TDI  
2009 – 2011 Volkswagen Jetta 2.0L TDI

**Conditions:** The operator of the vehicle may complain that the engine cranks but fails to start in cold temperatures (below 0°C or 32°F). The malfunction indicator lamp may be on, but not in all cases.

**Cause:** A potential cause for the above conditions is moisture being trapped and condensing in the air intake system, freezing and blocking the air intake.

**Correction:** Follow the manufacturer's recommended diagnostic and repair procedures when applicable, which may include installing a "cold weather kit," manufacturer's part number 1K0 198 803B.

