



TECH TIPS

Dixie Part Numbers: S-8427 S-8428 S-8982

Applications: 1998 Mazda 626 with the optional immobilizer system.

Condition: The technician may observe that the vehicle fails to start after replacing the transponder-equipped key.

Cause: This may be due to a poor contact or corrosion in the wiring and/or connector. The increase in resistance can cause the voltage to drop below minimum acceptable limits during the reprogramming procedure.

Correction: Follow the manufacturer's recommended procedures by installing replacement power (positive and negative leads) to the immobilizer system.

