



# TECH TIPS

**Dixie Part Numbers:**      A-8388      A-8736      S-8345      S-8988

**Applications:**      1998 Mitsubishi Montero Sport

**Condition:**      The technician may observe that when performing any work on the above application that the service diagrams are incorrect.

**Cause:**      The manufacturer had released manuals with incorrect configuration and circuit diagrams.

**Correction:**      Make sure when working on the above applications to obtain documentation that has the correction noted in TSB-98-54-002 updated.

