



TECH TIPS

Dixie Part Numbers: A-8203 S-8160

Applications: 1983 Mitsubishi Starion

Condition: 1) The wiring diagrams and configurations in the initial release are incorrect and/or missing information.
2) Adding transmitting devices – Warning.

Cause: There were several errors and omissions from the original service manual for the above application.

Correction: Verify that the manuals and wiring diagrams being used cover updates released in the following service bulletins:

- STB-83-08-003
- STB-83-08-013
- STB-83-08-014

DANGER: Some of the information contained in the updates pertains to the ABS system malfunctioning when transmitting devices such as citizens band radios (CBs), cellular phones etc. are installed.