



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 Mazda 6 with push button start

Condition: The operator or technician may observe that the engine fails to start after an optional remote starter system has been added.

Cause: A potential cause for the above is interference created by improperly installing a remote starting system in the vehicle.

Correction: Follow the manufacturer's procedures for installing remote starting systems to prevent issues.

