



# TECH TIPS

**Dixie Part Numbers:** S-80017

**Applications:** 2005 Acura TSX

**Condition:** The above vehicles were subject to a recall for a failure to start.

**Cause:** The recall notice identifies the source of the problem as a loose coil wire inside the fuel pump relay that was prone to breaking resulting in the engine shutting down and not restarting.

**Correction:** The manufacturer recommends replacing the fuel pump relay. The dealership network is to perform this task free of charge.

