



TECH TIPS

Dixie Part Numbers: A-80209

Applications: 2005 – 2008 Nissan Frontier 2.5L

Condition: The operator of the vehicle may complain of noise coming from the engine compartment generated by the drive belt.

Cause: There are several potential causes for the above condition including:

- The auto-tensioner failing.
- Oil contamination on the belt.
- An improperly aligned belt (from the factory).

Correction: Inspect the belt for the above conditions. Follow the manufacturer's recommended procedures for inspecting the belt alignment and making corrections (if required).

