



# TECH TIPS

**Dixie Part Numbers:** S-8687

**Applications:** 1996 – 2002 3.5 RL

**Condition:**

A grinding noise is heard intermittently while starting the engine.

**Cause:**

The manufacturer has identified that a potentially improperly manufactured flywheel may be the cause.

**Correction:**

The flywheel should be replaced (dealer part number 26250-PY3-010).

