



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2007 – 2009 Jeep Wrangler (International) Diesel (XD4)

Condition: The operator of the vehicle may complain of slow cranking and hard starting conditions.

Cause: A potential cause for the above is the calibration system for the charging rate. The factory installed calibration was undercharging the battery resulting in a weak or dead battery.

Correction: Follow the manufacturers' recommended procedures to update the calibration files if applicable.