



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Subaru Legacy 2.5L CVT see note
2010 Subaru Outback 2.5L CVT see note
Note: For both the CAL. and FED. models.

Condition: The operator of the vehicle may complain of long hard cranking cycles in cooler temperatures (-10C to 4C).

Cause: A potential cause for this is the logic programmed in the engine control module.

Correction: Follow the manufacturer's recommended procedures to update the engine control module logic file.

