



TECH TIPS

Dixie Part Numbers: S-8774 S-8775 S-8777

Applications: 2001 – 2002 Hyundai Santa Fe

Condition: The operator of the vehicle may complain of a crank without starting condition.

Cause: A potential cause for the above condition is a manufacturing flaw in the crankshaft positioning sensor.

Correction: Follow the manufacturer's recommended procedures for testing, and when required, replacing the crankshaft positioning sensor.

