



TECH TIPS

Dixie Part Numbers: S-8738

Applications: 2005 – 2008 Pontiac Vibe 1.8L 2 Wheel Drive Models

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- The engine fails to start.
- The engine runs rough.
- The engine stalls.
- The transmission shifting is harsh or rough.
- The malfunction indicator lamp is on.

Cause: A possible cause for the above conditions a faulty powertrain control module.

Correction: Follow the manufacturers recommended diagnostic and repair procedures which include inspecting and/or replacing the power train control module.

