



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 Buick Enclave
2009 Chevrolet Cobalt
2009 Chevrolet HHR
2009 Chevrolet Malibu
2009 Chevrolet Traverse
2009 GMC Acadia
2009 Pontiac G5
2009 Pontiac G6
2009 Saturn Aura
2009 Saturn Outlook
2011 Chevrolet Colorado
2011 GMC Canyon

Condition: The operator of the vehicle may complain of intermittent no crank condition, the vehicle rolls/moves while cranking, or that the vehicle rolls when in “park”.

Cause: A potential cause for the above conditions is an improperly installed adjustment clip on the automatic transmission shifter cable.

Correction: Follow the manufacturers recommended diagnostic and repair procedures when applicable.